

DATE 1107Z 10 JUL 62

TOP SECRET

1	4
2	5
3	6

TO : DIRECTOR

FROM : [REDACTED]

ACTION: OPS (1-2-3-4-5)

INFO : S/C (6)

DCM

TOR: 1135Z 10 JUL 62

OPERATIONAL IMMEDIATE
OPERATIONAL IMMEDIATE

IN 42073

TO OPIM [REDACTED]

INFO PRITY [REDACTED]

CITE [REDACTED]

0016

NIMBUS 3085

1. CONFIRMING TELECON [REDACTED]

MSN DELAYED

AT LEAST 24 HRS.

2. DURING PREFLT INSP [REDACTED] MAINT FOUND INOP IGNITER
PLUG. PROBABLE CAUSE IS BAD ENG IGNITION EXCITER BOX. ENG
ROLLBACK REQUIRED TO FIX. NO CAPABILITY OR IGNITION CIRCUIT
PARTS [REDACTED]

3. PLAN LAUNCH ARTICLE 10/1200Z GF 62-33. ETA [REDACTED]
10/1444Z. [REDACTED] CALL SIGN [REDACTED]

4. ARTICLE WILL FLY [REDACTED] MINUS FIVE. HAVE ONE IGNITER
PLUG. CONSIDER SATISFACTORY THIS TYPE FLT.

5. [REDACTED] DET REMAINING IN PLACE.

END OF MESSAGE

25 YEAR RE-REVIEW

TOP SECRET

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.